

TEMPERATURE CONVERSION

Farenheit Conversion ° F = $9/5$ °C + 32

Celcius Conversion ° C = $5/9$ (°F – 32)

Celcius Conversion ° C = °K – 273.15

